

AccuScience™ Analysis Report

QLab, 256 Bridge St, Metuchen, NJ 08840 info@qlabusa.com www.QLABusa.com

QLab Job No.: ME180914-14

Date Sampled: 9/14/2018

Date Received: 9/14/2018

Date Reported: 9/17/2018

AIHA EMPAT Lab ID: 178794

Analysis: AccuScience Premium Direct Exam (FD-02HP)

Client: RK Environmental

Phillipsburg, NJ

Contact: McGuinness, Michael

Project ID: Barley Sheaf ES

Reviewed by: WT

Approved by: Wei-Chih Tang, Ph.D., Lab Director

La Ten

Neviewed by: W	Approve	d by: wel-Chin i	ang, Ph.L	D., Lab Director	Lu	lu
Lab Sample No.	ME′	180914-14(1)	ME180914-14(2)		ME180914-14(3)	
Sample ID		01T	02T		03T	
Sample Location	ı	Faculty Rm		Rm 49	Rm 39	
Sample Type (Device)	Surface (Gel-Tape)		Surface (Gel-Tape)		Surface (Gel-Tape)	
Date Analyzed		9/17/2018	9	9/17/2018	9/17/2018	
	(1) Peak Density (within 1 mm dia.)*		(1) Peak Density (within 1 mm dia.)*		(1) Peak Density (within 1 mm dia.)	
Identification	Spores	Hyphae/Structure	Spores	Hyphae/Structure	Spores	Hyphae/Structure
Major Hydrophilic Fungi:***		. ,,	·			
Stachybotrys						
Chaetomium						
Ulocladium						
Acremonium						
Trichoderma						
Aureobasidium						
Yeasts (cells)		•		•		
Other Fungi:						
Aspergillus/Penicillium-like	+					
Aspergillus						
Penicillium						
Cladosporium			+			
Alternaria						
Curvularia						
Epicoccum						
Myxomycetes/smuts/Periconia						
Nigrospora						
Pithomyces						
Unidentifiable w/o culturing	+		+		+	
Summary	(2) Overall Coverage		(2) Overall Coverage		(2) Overall Coverage	
Sample Size Examined	150 mm²		150 mm²		150 mm²	
Mycologix™ Fungal Biomass Level#	1: Normal Background		1: Normal Background		1: Normal Background	
Mold/Yeast Growth Observed	No		No		No	
Sample Mold/Yeast Coverage**	Trace: < 3%		Trace: < 3%		Trace: < 3%	
Sample Debris Coverage**	Tı	race: < 3%	Medium: 10 - 50%		Trace: < 3%	
Note						
	·		·		<u> </u>	

[#] Mycologix™ Fungal Biomass Level: 1: Normal Background, 2A: Settled Biomass, 2B: Residual Biomass 3A: Slight Growth, 3B: Moderate Growth, 3C: Heavy Growth

^{*}Peak Density: Peak density of fungal biomass (spores, reproduction structures, hyphae, etc.) observed under the microscope within the viewfield of 200X magnification (approximately 1 mm in diameter). ++++, +++, ++ Biomass covering >50%, 10-50%, 3-10%, <3% of the 200X viewfield, respectively

^{**} Sample Coverage of Fungi/Debris: Overall coverage of fungal biomass/debris collected on the tape samples
Tape/slide samples are taken from bulk/swab samples received and then analyzed under microscope.

High, Medium, Low, Trace: Biomass/debris covering >50%, 10-50%, 3-10%, <3% of the entire sample, respectively

^{***}Hydrophilic Fungi: Water-loving fungi, Min. Aw >0.89. Absence of hydrophilic fungi does not exclude the possibility of a water damage history.



AccuScience™ **Analysis Report**

QLab, 256 Bridge St, Metuchen, NJ 08840 info@qlabusa.com www.QLABusa.com

AIHA EMPAT Lab ID: 178794

Analysis: AccuScience Premium Direct Exam (FD-02HP) Client: **RK Environmental**

Phillipsburg, NJ

Contact: McGuinness, Michael

Project ID: Barley Sheaf ES

QLab Job No.: ME180914-14 **Date Sampled: 9/14/2018** Date Received: 9/14/2018 Date Reported: 9/17/2018

Lab Sample No.	ME1	80914-14(4)	ME180914-14(5)		ME180914-14(6)	
Sample ID		04T	05T		06T	
Sample Location		Rm 36	Rm 26		Rm 28	
Sample Type (Device)	Surfa	ce (Gel-Tape)	Surface (Gel-Tape)		Surface (Gel-Tape)	
Date Analyzed	S	9/17/2018	9	9/17/2018	9/17/2018	
·	(1) Peak Density (within 1 mm dia.)*		(1) Peak Density (within 1 mm dia.)*		(1) Peak Density (within 1 mm dia	
Identification	Spores	Hyphae/Structure	Spores	Hyphae/Structure	Spores	Hyphae/Structure
Major Hydrophilic Fungi:***						
Stachybotrys						
Chaetomium						
Ulocladium						
Acremonium						
Trichoderma						
Aureobasidium						
Yeasts (cells)						
Other Fungi:						
Aspergillus/Penicillium-like			+			
Aspergillus						
Penicillium						
Cladosporium						
Alternaria						
Curvularia						
Epicoccum						
Myxomycetes/smuts/Periconia	+					
Nigrospora						
Pithomyces						
Unidentifiable w/o culturing	+		+		+	
Summary	(2) Overall Coverage		(2) Overall Coverage		(2) Overall Coverage	
Sample Size Examined	150 mm²		150 mm²		150 mm²	
Mycologix™ Fungal Biomass Level#	1: Nor	mal Background	1: Normal Background		1: Normal Background	
Mold/Yeast Growth Observed	No No		No	No		
Sample Mold/Yeast Coverage**	Trace: < 3%		Trace: < 3%		Trace: < 3%	
Sample Debris Coverage**	Trace: < 3%		Trace: < 3%		Trace: < 3%	
Note						

[#] Mycologix™ Fungal Biomass Level: 1: Normal Background, 2A: Settled Biomass, 2B: Residual Biomass 3A: Slight Growth, 3B: Moderate Growth, 3C: Heavy Growth

^{*}Peak Density: Peak density of fungal biomass (spores, reproduction structures, hyphae, etc.) observed under the microscope within the viewfield of 200X magnification (approximately 1 mm in diameter). ++++, ++, ++; Biomass covering >50%, 10-50%, 3-10%, <3% of the 200X viewfield, respectively

^{**} Sample Coverage of Fungi/Debris: Overall coverage of fungal biomass/debris collected on the tape samples Tape/slide samples are taken from bulk/swab samples received and then analyzed under microscope. High, Medium, Low, Trace: Biomass/debris covering >50%, 10-50%, 3-10%, <3% of the entire sample, respectively

^{***}Hydrophilic Fungi: Water-loving fungi, Min. Aw >0.89. Absence of hydrophilic fungi does not exclude the possibility of a water damage history.



AccuScience™ Analysis Report

QLab, 256 Bridge St, Metuchen, NJ 08840 info@qlabusa.com www.QLABusa.com AIHA EMPAT Lab ID: 178794

Analysis: AccuScience Premium Direct Exam (FD-02HP)

Client: RK Environmental

Phillipsburg, NJ

Contact: McGuinness, Michael Project ID: Barley Sheaf ES

QLab Job No.: ME180914-14 **Date Sampled:** 9/14/2018 **Date Received:** 9/14/2018 **Date Reported:** 9/17/2018

ME1	80914-14(7)	ME1	180914-14(8)		
	07T	08T			
	Rm 23	Rm 24			
Surface (Gel-Tape)		Surface (Gel-Tape)			
g	9/17/2018	9/17/2018			
(1) Peak Density (within 1 mm dia.)*		(1) Peak Density (within 1 mm dia.)*			
,	, ,,	,	, , ,		
+		+			
(2) Overall Coverage		(2) Overall Coverage			
150 mm²		150 mm²			
1: Nor	mal Background	1: Normal Background			
	No		No		
Trace: < 3%		Trace: < 3%			
Tr	ace: < 3%	Trace: < 3%			
	Surfa (1) Peak Do Spores + (2) Ov 1: Norta	Rm 23 Surface (Gel-Tape) 9/17/2018 (1) Peak Density (within 1 mm dia.)* Spores Hyphae/Structure Hyphae/Structure + (2) Overall Coverage 150 mm² 1: Normal Background No Trace: < 3% Trace: < 3%	Normal Background Normal Rm 23 Surface (Gel-Tape) Surface (Gel-Tape) Surface (Gel-Tape) Surface (Gel-Tape) Surface (Gel-Tape) Spores Spores Hyphae/Structure Spores Spo	No No No No No No No No	No No No No Trace: < 3% Name and No No No Trace: < 3% Name and No No Trace: < 3% Name and No No Trace: < 3% Name and No No No Trace: < 3% Name and No No No Trace: < 3% Name and No No No No No No No N

[#] Mycologix™ Fungal Biomass Level: 1: Normal Background, 2A: Settled Biomass, 2B: Residual Biomass 3A: Slight Growth, 3B: Moderate Growth, 3C: Heavy Growth

^{*}Peak Density: Peak density of fungal biomass (spores, reproduction structures, hyphae, etc.) observed under the microscope within the viewfield of 200X magnification (approximately 1 mm in diameter). ++++, +++, ++ Biomass covering >50%, 10-50%, 3-10%, <3% of the 200X viewfield, respectively

^{**} Sample Coverage of Fungi/Debris: Overall coverage of fungal biomass/debris collected on the tape samples Tape/slide samples are taken from bulk/swab samples received and then analyzed under microscope.

High, Medium, Low, Trace: Biomass/debris covering >50%, 10-50%, 3-10%, <3% of the entire sample, respectively

^{***}Hydrophilic Fungi: Water-loving fungi, Min. Aw >0.89. Absence of hydrophilic fungi does not exclude the possibility of a water damage history.